


X45WK

Installation Instructions

- 1** Fasten mounting plate to wall with mounting screws. Ensure slot for stem is vertical.
- 2** Insert fixture stem into mounting plate. Secure in place by screwing front plate onto mounting plate.
- 3** Connect fixture leads to 60W minimum 12V transformer. Next, connect primary to driver input wires then fit into electrical box.

For remote driver connect fixture wires to low voltage wiring.



INPUT PRIMARY 120/277V
12V Transformer



CAUTION

- Read all instructions.
- Risk of fire and electrical shock. Turn off power before installation.
- Do not over tighten screws.
- Connect to 12V electronic transformer.
- Use only low voltage electronic dimmers.
- Maximum 50W lamp.
- Test installation by leaving fixture on for 20-30 minutes to ensure proper operation.
- Keep this document as a reference.

Parts

	Qty.
• X45WK unit	1
• Mounting plate	1
• Mounting screws	2
• Front plate	1
• Fixing screws	2

Tools

- Phillips screwdriver *not included*

 **MPLIGHTING**®

T 604 708 1184 mplighting.com

Copyright © MP Lighting All technical information in this document is subject to change.

Version 05-2008