
CS Fixture Connector



2 Slide each side of connector onto CBL001 cable in desired location.



Tighten both sides until secure.

X31 CS Installation Instructions

\rm AUTION

- Read all instructions.
- Do not move fixture along rail while power is on.
- Ensure connector caps are tight to prevent short circuit from occurring.
- Leave system on to test installation for 20-30 minutes. Heat indicates a loose connection. Check if any connections on the system are warmer than your body temperature. If a connection is very warm, turn off system and retighten that connection.
- Keep this document as a reference.

